

HEATH TECNA

Job Posting

Title: Quality Assurance Inspector
Reports To: Quality Assurance Supervisor
Application Deadline: Until Filled
Posting: Internal/External

Responsibilities:

The Quality Assurance Inspector I physically inspects aircraft components and hardware to ensure that workmanship and raw materials meets acceptable standards of quality and/or airworthiness, and reviews associated documentation to ensure that all design data (dimensional, material, appearance, special processes) are substantiated, and that aircraft components are in an airworthy condition with all required documentation properly completed and filed.

- Responsible for Quality Assurance / Quality Control inspections of aircraft components.
- Keeps accurate, neat and legible records.
- Coordinates throughout assigned jobs with other departments to ensure that accurate, neat and legible records are maintained.
- Ensures that raw materials meet material specifications and that aircraft components meet engineering requirements prior to release from QA quarantine area or final buy-off.
- Complies with company safety requirements at all times.
- Continually monitors Heath Tecna's compliance with ISO9001, AS9100, and FAR Part 21 as applicable.
- Perform other duties as required by immediate Supervisor or Quality Manager.

Requirements:

- High School diploma or GED required. Experience in a manufacturing or quality environment.
- Working knowledge of engineering drawings / specifications and basic quality procedures.
- Must be proficient in the use of precision measurement equipment; micrometers, calipers, height gauges, dial indicators, surface roughness gauges, etc.
- Strong written and verbal communication skills. Strong computer skills.
- Must be able to prioritize tasks, work independently and efficiently.
- Lifting requirement: 30 lbs.
- Ability to work any shift and holidays on rotation, if required.

Equal Opportunity Employer